

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2024

Submitted Date:

06/20/2024

Document Number:

694500680

FIELD INSPECTION FORMLoc ID 312761 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		htrujillo@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222214	WELL	PR	05/01/2023	OW	081-05172	GOV'T-POHLMAN 2	EI

General Comment:

Environmental staff, Kris Neidel inspected the well pad. The well was Shut In (SI) at the time of inspection. The following was observed on the pad; pumping unit with electric motor, a flowline leave the pad and appears to cross the #2 pad. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached See attached Photos.

Inspected Facilities

Facility ID: 222214 Type: WELL API Number: 081-05172 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500681	photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6595302