

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403828204

Date Received:  
06/18/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mollie O'Hare</u>	<u>970-563-4000</u>	<u>mollieo@maralexinc.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000740  
Inspection Date: 05/02/2024 FIR Submit Date: 05/06/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 333661

Location Name: KEEGAN PRTRICK-N33N7W Number: 11NWNW County: \_\_\_\_\_  
Qtrqtr: NWN Sec: 11 Twp: 33N Range: 7W Meridian: N  
W  
Latitude: 37.122820 Longitude: -107.582665

FACILITY - API Number: 05-067- -00 Facility ID: 333661

Facility Name: KEEGAN PRTRICK-N33N7W Number: 11NWNW  
Qtrqtr: NWN Sec: 11 Twp: 33N Range: 7W Meridian: N  
W  
Latitude: 37.122820 Longitude: -107.582665

CORRECTIVE ACTIONS:

**2**  CA# 194932

Corrective Action: comply with rule 608 Install or repair wildlife protection equipment. Date: 05/11/2024

Response: CA COMPLETED Date of Completion: 06/17/2024

Operator Comment: We tightened the netting and at the request of Cory McDonough, placed a wooden stick in the pan for critters in case they get trapped. Please be aware that this location has a serious snake problem. A seven-foot bull snake lives under this pan. A pumper pulled a 12-foot snake out of the meter house recently, and a third snake, about six feet long, has also been hanging out on this location. It is likely that small mammals are the draw for these reptiles.

ECMC Decision: Approved via an AMI

ECMC  
Representative:

Per photo included in attachment provided by operator wildlife BMPs have been installed/repared.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: We tightened the netting and at the request of Cory McDonough, placed a wooden stick in the pan for critters in case they get trapped.  
Please be aware that this location has a serious snake problem. A seven-foot bull snake lives under this pan. A pumper pulled a 12-foot snake out of the meter house recently, and a third snake, about six feet long, has also been hanging out on this location. It is likely that small mammals are the draw for these reptiles.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mollie O'Hare

Signed: \_\_\_\_\_

Title: E.A.

Date: 6/18/2024 11:58:13 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403828204	FIR RESOLUTION SUBMITTED
403828248	PHOTOS - DAY TANK WILD LIFE ISSUE RESOLVED

Total Attach: 2 Files