

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2024

Submitted Date:

06/27/2024

Document Number:

699505996

FIELD INSPECTION FORMLoc ID 320225 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

9 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Brown, Kari		kari.oakman@state.co.us	
,		gfritzler@bresnan.net	
Graber, Nikki		nikki.graber@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	TA

General Comment:

There have been no changes to equipment on location since previous inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Lease road is not maintained.		
Corrective Action:	Comply with rule 204	Date:	06/06/2024
Type	OTHER		
Comment:	Anchors are not marked with highly visible markers.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	06/27/2024
Type	OTHER		
Comment:	OOSLOT risers not tagged		
Corrective Action:	Comply with rule 1105	Date:	06/06/2024
Type	OTHER		
Comment:	Weeds unmanaged on locaion		
Corrective Action:	Comply with rule 606	Date:	06/06/2024
Type	OTHER		
Comment:	Pit appears to be closed on location, provide form 27, no form 27 on file. Pit was observed on previous inspections.		
Corrective Action:	Comply with rule 911 a	Date:	06/06/2024
Type	OTHER		
Comment:	stormwater damage on south end of location by wellhead		
Corrective Action:	Comply with rule 1002.f.(2)C	Date:	06/06/2024
Type	OTHER		
Comment:	Berms inadequate around tank		
Corrective Action:	Comply with rule 603 o.	Date:	06/06/2024
Type	OTHER		
Comment:	wellhead sign inadequate		
Corrective Action:	Comply with rule 605 d.	Date:	06/06/2024
Type	OTHER		
Comment:	Tanks sign is inadequate		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	06/27/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Inspected FacilitiesFacility ID: 203117 Type: WELL API Number: 001-08525 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 11/21/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On 6/26/24 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Linnebur 24-1</p> <p>Company Name- Fritzler resources INC</p> <p>API- 05-001-08525</p> <p>In AdamsCounty Colorado.</p> <p>While there, I observed TA well</p> <p>This is a follow up inspection from document # 699505911 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Pit closed no form 27. Rule 911 a. 6/6/24</p> <p>OOSLOT LOTO. Rule 1105. 6/6/24</p> <p>wellhead sign. Rule 605 d. 6/6/24</p> <p>stormwater. Rule 1002.f(2)C. 6/6/24</p> <p>Berms. Rule 603 o. 6/6/24</p> <p>Weeds. Rule 606. 6/6/24</p> <p>Access. Rule 204. 6/6/24</p> <p>Tank sign. Rule 605 a. 6/27/24</p> <p>Deadmen anchors. Rule 1003. A. 6/27/24</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	06/27/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505997	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605542