

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2024

Submitted Date:

07/01/2024

Document Number:

713301019**FIELD INSPECTION FORM**Loc ID 406267 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 93200Name of Operator: VESSELS OIL & GAS COMPANYAddress: 8435 W 88TH AVECity: ARVADA State: CO Zip: 80005**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARTFIELD, RICHARD	303-421-9379	rhartfield@hjstax.com	GENERAL COUNSEL
Silver, Randy	720-827-6688	randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240343	WELL	PA	09/16/1996	GW	123-08131	WILLIAM H PELTIER 1	PA

**General Comment:**

MRU inspectin

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment:	safety fencing				
Corrective Action:					Date:
Equipment:					
Type:	#				corrective date
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 240343

Type: WELL

API Number: 123-08131

Status: PA

Insp. Status: PA

Workover

Comment: MIRU rescheduled, sound walls to be installed 7-9-24, refile form 42

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Have to reschedule MIRU after sound walls to be installed, refile form 42 also	kesterm	07/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301020	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6608820">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6608820</a>