

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403842418

Date Received:
07/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Ross, Rikki	970-896-5665	rikki.ross@fulcrumeo.com
Penner, annalee		annalee@fulcrumef.com
. Fulcrum		inspections@fulcrumeo.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 707800932
Inspection Date: 05/01/2024 FIR Submit Date: 05/09/2024 FIR Status:

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC Company Number: 10805
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 333288

Location Name: MUTUAL PAD Number: 4-30 County:
Qtrqtr: SWSE Sec: 30 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.541977 Longitude: -106.414359

FACILITY - API Number: 05-057-00 Facility ID: 333288

Facility Name: MUTUAL PAD Number: 4-30
Qtrqtr: SWSE Sec: 30 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.541977 Longitude: -106.414359

CORRECTIVE ACTIONS:

1 CA# 195003

Corrective Action: Eliminate possibility of wildlife to enter open ECD Date: 05/24/2024

Response: CA COMPLETED Date of Completion: 05/17/2024

Operator Comment: Fulcrum has eliminated the possibility of wildlife to enter open ECD.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 CA# 195004

Corrective Action: Remove debris

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 05/17/2024

Operator
Comment: Debris has been removed from location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

3 CA# 195005

Corrective Action: Provide proper labeling

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 05/17/2024

Operator
Comment: Tote missing labeling has been removed from the location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

4 CA# 195006

Corrective Action: Provide proper signage

Date: 06/26/2024

Response: CA COMPLETED

Date of Completion: 06/26/2024

Operator
Comment: API number has been added to tank signage.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

5 CA# 195007

Corrective Action: Remove, put into service or provide proper documentation for stored equipment.

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 05/17/2024

Operator
Comment: Trailer has been removed from location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: _____

Title: EHS Field Advisor

Date: 7/1/2024 6:46:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403842418	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files