

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403842423

Date Received:

07/02/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

annalee Penner

annalee@fulcrumef.com

Fulcrum

inspections@fulcrumeo.com

Ross, Rikki

970-896-5665

rikki.ross@fulcrumeo.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 707800924

Inspection Date: 05/01/2024

FIR Submit Date: 05/08/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC

Company Number: 10805

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 449274

Location Name: Rabbit Ears 0681

Number: 23

County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 23 Twp: 6N Range: 81W Meridian: 6

Latitude: 40.476982 Longitude: -106.454006

FACILITY - API Number: 05-057-

-00

Facility ID: 449274

Facility Name: Rabbit Ears 0681

Number: 23

Qtrqtr: SWNE Sec: 23 Twp: 6N Range: 81W Meridian: 6

Latitude: 40.476982 Longitude: -106.454006

CORRECTIVE ACTIONS:

1 ☒ CA# 195018

Corrective Action: Remove debris

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 05/17/2024

Operator  
Comment: Debris removed from location.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

2 ☒ CA# 195019

Corrective Action: Provide proper signage

Date: 06/19/2024

Response: CA COMPLETED

Date of Completion: 06/26/2024

Operator  
Comment:

Battery signage has been added to the tank battery.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

3 ☒ CA# 195020

Corrective Action: Evacuate fluids in containments to provide adequate space in case of a spill

Date: 05/24/2024

Response: CA COMPLETED

Date of Completion: 06/05/2024

Operator  
Comment:

Containment sucked out.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: \_\_\_\_\_

Title: EHS Field Advisor

Date: 7/2/2024 1:34:40 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403842423	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files