

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2024

Submitted Date:

07/03/2024

Document Number:

694500692

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**  
ECMC Operator Number: 10386  
Name of Operator: POC-I LLC  
Address: P.O. BOX 51208  
City: CASPER State: WY Zip: 82605

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Chamard, Megan		megan.chamard@state.co.us	
Podio, Rebecca	307-746-6468	rpodio@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483727	SPILL OR RELEASE	CL			-	Ilse Dome Discharge	EI

**General Comment:**  
On 7/2/2024, ECMC staff; Kris Neidel inspected Seeping Spring Gulch, as a result of Spill/Release #483727 and Remediation project 28246 Weather was 75 degrees. The following was observed: Some water in the gulch. Corrective Actions: The water in the gulch should be sampled and analyzed for Table 915-1 Organic Compounds in Groundwater and Groundwater Inorganic Parameters. The results should be reported on a supplemental Form 27. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached From Form 27 Doc # 403723111:COA: "Operator anticipates the remaining cost for this project to be: \$200,000. Within 30-days of Staff approval of F27 Doc #403723111, Operator to provide a detailed task and cost breakdown for the \$200,000." Corrective Actions; Submit a report of work completed on a Supplemental Form 27 (Remediation Number 28244), the last update was March 19, 2024(doc # 403723111). The Operator shall collect a sample for the pooled water for Table 915-1 Organic Compounds in Groundwater and Groundwater Inorganic Parameters (see photo#12 attached).See attached Photos.

**Inspected Facilities**

Facility ID: 483727 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500693	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6611569">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6611569</a>