

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2024

Submitted Date:

06/27/2024

Document Number:

713601196**FIELD INSPECTION FORM**Loc ID 314210 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
BEAR STACY L		stacy@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261890	WELL	SI	09/01/2021	GW	099-06872	SPARTAN 1	RI

**General Comment:**

This is a follow up of the previous inspection #713600831 at the SPARTAN #1 wellsite.  
The previous inspection corrective actions have not been completed.  
See attached photos and additional details within this report.

Note: Documentation (FIRR) showing completion of corrective actions is requested within 2 weeks.  
Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Location****Lease Road:**

Type	Access		
comment:	There are deep ruts in the road and there are now vehicle tracks driving off the two track which is widening the road. The vehicle ruts need to be repaired and stabilized. Previous corrective action was not completed.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	There is no sign posted at the wellhead. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment pipe laying on the ground that needs to be removed. Previous corrective action was not completed.		
Corrective Action:	Comply with Rule 606.	Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	TANK BATTERY		
Comment:	The fence around the tank and pumpjack are not maintained to prevent livestock entry. There are wires sticking out that could injury livestock. Previous corrective action was not completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403839382	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604882">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604882</a>
713601197	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604878">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6604878</a>