

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2024

Submitted Date:

07/01/2024

Document Number:

713601200**FIELD INSPECTION FORM**Loc ID 308840 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	
Sanchez, Chris		chris.sanchez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
308840	LOCATION	AC			-	BEIL 33-7 Tr-632S67W 7NWSE	RI

**General Comment:**[This is a location inspection at the BEIL #33-7 Tr wellsite.](#)

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Recent weed control has been performed at wellsites in the area.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	There is unused sound walls on location that should be removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Comment	There is E&P Waste from Pit Facility 285087 stored on location. It is unknown if there is a liner but the grey material is contained in a berm. It appears this material has been stored on location since last year and needs to be removed.			
Corrective Action	Comply with Rule 905.			Date:

Spill/Remediation:

Comment:			
Corrective Action:		Date:	

Emission Control Burner (ECB):	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403841540	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607960">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607960</a>
403844105	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6610486">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6610486</a>
713601201	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607958">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6607958</a>