

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403833058

Date Received:
06/24/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dolezal, Pat

970-332-3585

pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 698601955

Inspection Date: 04/09/2024

FIR Submit Date: 04/29/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 304856

Location Name: ROCKWELL-61N45W Number: 7SWSE County: YUMA

Qtrqtr: SWSE Sec: 7 Twp: 1N Range: 45W Meridian: 6

Latitude: 40.063080 Longitude: -102.442912

FACILITY - API Number: 05-125- -00 Facility ID: 275557

Facility Name: ROCKWELL Number: 34-7

Qtrqtr: SWSE Sec: 7 Twp: 1N Range: 45W Meridian: 6

Latitude: 40.063080 Longitude: -102.442912

CORRECTIVE ACTIONS:

1 ☒ CA# 194757

Corrective Action: Install sign to comply with Rule 605.a

Date: 04/03/2024

Corrective action date remains the same to document period of non-compliance.

Response: CA COMPLETED

Date of Completion: 06/21/2024

Operator Comment: Decals were replaced earlier, area foreman was not notified by previous lease attendant that it had been done.

ECMC Decision: Approved



Install sign to comply with Rule 605.a

Corrective action date remains the same to document period of non-compliance.

Corrective action date remains the same to document period of non-compliance.

Date of Completion: 06/21/2024

Decals were replaced earlier, area foreman was not notified by previous lease attendant that it had been done.

Approved

Comment:

Print Name: Pat Dolezal

Date: 6/24/2024 9:09:57 AM

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403833058	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Page 2 of 2