

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403846589

Date Received:

07/08/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000806

Inspection Date: 05/30/2024

FIR Submit Date: 06/10/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 385860

Location Name: POLE BARN MONITOR WELL-N35N7W Number: 15NESE County: _____

Qtrqr: NESE Sec: 15 Twp: 35N Range: 7W Meridian: N

Latitude: 37.298416 Longitude: -107.615992

FACILITY - API Number: 05-067- -00 Facility ID: 385860

Facility Name: POLE BARN MONITOR WELL-N35N7W Number: 15NESE

Qtrqr: NESE Sec: 15 Twp: 35N Range: 7W Meridian: N

Latitude: 37.298416 Longitude: -107.615992

CORRECTIVE ACTIONS:

1 ☒ CA# 195769

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 07/10/2024

Response: CA COMPLETED

Date of Completion: 06/24/2024

Chemical treatment of weeds completed. Seeded and treated field bindweed and undesirable species.

Operator
Comment:

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action complete. See attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 7/8/2024 8:53:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403846589	FIR RESOLUTION SUBMITTED
403846612	Pole Barn Monitor Well 1 Corrective Action photos

Total Attach: 2 Files