

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2024

Submitted Date:

07/11/2024

Document Number:

713601226

## FIELD INSPECTION FORM

Loc ID 334553 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oxy		ECMCInspections@Oxy.com	
Newville, Toni		toni_newville@oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211835	WELL	PA	12/08/2022	CO2	055-06072	SHEEP MOUNTAIN UNIT 4-4-P	RI
334553	LOCATION	AC			-	Sheep Mountain Unit 6-4-I	RI

**General Comment:**

This is a follow up of the previous inspection (#713600946) at the Sheep Mountain Unit 6-4-I location.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	There has been recent noxious weed control performed at the location.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	The pile of brush debris still remains at the northeast side of the location which will need to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	07/19/2024
Type	TRASH		
Comment:	The trash was picked up since previous inspection.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	The orange safety fence is still in disrepair and should be removed if no longer needed. The wellhead has been partly backfilled and is no longer a danger for wildlife or livestock.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Environmental					
<b>Waste Management:</b>					
Type	Management	Condition	GPS (Lat) (Long)		
	Piles		37.721090	-105.222370	
Comment	The pile of E&P waste stored at the northeast side of the location needs to be removed. This pile has been stored for nearly a year and must be removed and properly disposed.				
Corrective Action	Comply with Rule 905.				Date: 07/19/2024
<b>Spill/Remediation:</b>					
Comment:					
Corrective Action:					Date: _____
Emission Control Burner (ECB): _____					
Comment:					
Pilot: _____	Wildlife Protection Devices (fired vessels): _____				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The road was regraded to allow stormwater drainage toward the culverts.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403850936	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6618467">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6618467</a>
713601227	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6618466">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6618466</a>