

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403815708

Date Received:

06/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Krystal Heibel		krystal.heibel@state.co.us
Abdul Elhajdi		abdul.elhajdi@state.co.us
Kyle Waggoner		kyle.waggoner@state.co.us
Kilian Collins		kilian.collins@state.co.us
Dolezal, Pat		pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100280

Inspection Date: 04/24/2024

FIR Submit Date: 05/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 337805

Location Name: KNODEL-64S42W Number: 16SENE County: _____

Qtrqtr: SENE Sec: 16 Twp: 4S Range: 42W Meridian: 6

Latitude: 39.713640 Longitude: -102.065090

FACILITY - API Number: 05-125-00 Facility ID: 337805

Facility Name: KNODEL-64S42W Number: 16SENE

Qtrqtr: SENE Sec: 16 Twp: 4S Range: 42W Meridian: 6

Latitude: 39.713640 Longitude: -102.065090

CORRECTIVE ACTIONS:

1 CA# 194949

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 07/07/2024

Response: CA COMPLETED

Date of Completion: 06/10/2024

Operator Comment:	Stained soil was removed and replaced.	
ECMC Decision: _____		
ECMC Representative:		

2 CA# 194950

Corrective Action:	Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This informations shall be submitted within the next Form 27 submittal.	Date: <u>07/07/2024</u>
Response: <u>CA COMPLETED</u> Date of Completion: <u>06/10/2024</u>		
Operator Comment:	Area foreman states that there is no historic salt kill along road. Erosion material from road pulled back onto road with grader. BMP applied	
ECMC Decision: _____		
ECMC Representative:		

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal Signed: _____

Title: Regulatory Specialist Date: 6/6/2024 10:12:34 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403815708	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files