

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403860636

Date Received:

07/22/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708901650

Inspection Date: 09/13/2023

FIR Submit Date: 09/14/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 335103

Location Name: PA-66S95W Number: 32NWSE County: \_\_\_\_\_

Qtrqtr: NWSE Sec: 32 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.479199 Longitude: -108.020050

### FACILITY - API Number: 05-045- -00 Facility ID: 335103

Facility Name: PA-66S95W Number: 32NWSE

Qtrqtr: NWSE Sec: 32 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.479199 Longitude: -108.020050

### CORRECTIVE ACTIONS:

1 ☒ CA# 181166

Corrective Action: Operators will prevent & minimize adverse impacts to wildlife resources.

Date: 09/21/2023

Response: CA COMPLETED

Date of Completion: 09/21/2023

Operator  
Comment:

Open ended pipe has been capped. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

2 ☒ CA# 181167

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 09/29/2023

Response: CA COMPLETED

Date of Completion: 10/16/2023

Operator  
Comment: Rills have been repaired. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #181166: Open ended pipe has been capped. Corrective Action complete.  
CA #181167: Rills have been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 7/22/2024 8:55:37 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403860636	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files