

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2024

Submitted Date:

07/29/2024

Document Number:

711901005**FIELD INSPECTION FORM**Loc ID 316954 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heibel, Krystal		krystal.heibel@state.co.us	
,		gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233467	WELL	PR	06/26/1990	OW	121-05510	WITTENBERG 1	PR

**General Comment:**

ROUTINE FIR - CA'S CITED WITHIN THIS FIR -

**Location****Lease Road:**

Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	SATISFACTORY	Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
Lube Oil	Pump Jack			
Comment:	REPAIR LEAK AT GEARBOX AND REMOVE/REMEDiate SOILS			
Corrective Action:	COMPLY WITH RULE 900 SERIES			Date: 07/31/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 0		corrective date
Comment:	NO CHANGE		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	233467	Type:	WELL	API Number:	121-05510	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	OW								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
711901056	PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642781">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642781</a>