

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403874251

Date Received:
08/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
4 of 5 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tyler Faldyn</u>	<u>832-748-1090</u>	<u>tfaldyn@americanhelium.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500371
Inspection Date: 07/08/2024 FIR Submit Date: 07/09/2024 FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 315416

Location Name: N. DOUGLAS CREEK-61S101W Number: 33NENW County: RIO BLANCO
Qtrqr: NENW Sec: 33 Twp: 1S Range: 101W Meridian: 6
Latitude: 39.924700 Longitude: -108.741033

FACILITY - API Number: 05-103-00 Facility ID: 230794

Facility Name: N. DOUGLAS CREEK Number: 3-33-1-1
Qtrqr: NENW Sec: 33 Twp: 1S Range: 101W Meridian: 6
Latitude: 39.924700 Longitude: -108.741033

CORRECTIVE ACTIONS:

2 CA# 196628

Corrective Action: Repair equipment. Remove and properly dispose of oily waste and stained soil. Date: 05/29/2023

Response: CA COMPLETED Date of Completion: 07/10/2024

Operator Comment: Pumping unit leak has been repaired. Stained soil removed from site. FIR responded to in FIRR Document #403848376.

ECMC Decision: _____

ECMC Representative:

3 CA# 196629

Corrective Action: Maintain noxious weed control on all disturbed areas as a result of Oil & Gas activities.

Date: 07/27/2023

Response: CA COMPLETED

Date of Completion: 07/10/2024

Operator Comment: Noxious weeds have been removed. FIR responded to in FIRR Document #403848376

ECMC Decision:

ECMC Representative:

4 CA# 196630

Corrective Action: All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.

Date: 05/26/2023

Response: CA COMPLETED

Date of Completion: 07/10/2024

Operator Comment: All trash, rubbish and debris have been removed. FIR responded to in FIRR Document #403848376.

ECMC Decision:

ECMC Representative:

5 CA# 196631

Corrective Action: Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month.

Date: 08/08/2024

Response: CA COMPLETED

Date of Completion: 05/14/2024

Operator Comment: Locin has submitted production reporting for this well on time (please see attached screenshots to show the submittal dates and the months of production and attached production report). This well's production is current and up to date.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Niah Wilson

Signed:

Title: Regulatory Specialist

Date: 8/1/2024 2:24:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403874307	March 2024 Production Reported, Including NDC 3-33-1-1
403874309	N Douglas Creek Production Reporting
403874311	Production Report Submissions with Dates

Total Attach: 3 Files