

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2024

Submitted Date:

07/24/2024

Document Number:

699506079

## FIELD INSPECTION FORM

Loc ID 320662 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204342	WELL	PR	01/01/2023	GW	005-06427	CHURCH 7-A 41-2	PR

**General Comment:**[There have been no changes to equipment on location since previous inspection.](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	WEEDS			
Comment:	weeds unmanaged on location			
Corrective Action:	Comply with rule 606			Date: 08/08/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

**Inspected Facilities**Facility ID: 204342 Type: WELL API Number: 005-06427 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 04/02/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

ECMC Inspection Report Summary  
On 7/24/24 I, Inspector Justin Medina conducted an on-site inspection at:  
Well Name- Church 7-A 41-2  
Company Name- KPK  
API- 05-005-06427  
In Arapahoe County Colorado.  
While there, I observed PR well  
During this inspection the following possible compliance issues were observed:  
Weeds unmanaged on location. Rule 606. 8/24/24  
A follow up on this site inspection needs to be conducted to ensure the compliance issues  
have been corrected to comply with ECMC rules.  
This is a summary of inspection report.

medinaj

07/24/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403868363	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6641978">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6641978</a>
699506080	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6641969">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6641969</a>