

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2024

Submitted Date:

07/29/2024

Document Number:

693807509**FIELD INSPECTION FORM**Loc ID 399572 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Gavito, Danielle		dgavito@americanhelium.us	
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Roberts, Jake		jroberts@americanhelium.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275967	WELL	TA	01/17/2005	GW	113-06173	HC MEX 14-13-44-15	TA

General Comment:

ECMC staff performed a routine field inspection on 7/23/2024.
Issues were found requiring corrective action. See inspection text and photos for details.

Location**Lease Road:**

Type	Access		
comment:			
Corrective ActionL		Date:	
Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	866-775-8385 Wrong Emergency contact number	
Corrective Action:	Install sign to comply with Rule 605.d.	Date: 08/30/2024

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

Equipment:

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities										
Facility ID:	275967	Type:	WELL	API Number:	113-06173	Status:	TA	Insp. Status:	TA	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>Last MIT to maintain SI/TA status 12/7/2015. Well TA longer than 6 months with no Form 4 submitted</div>								
Corrective Action:		<div>Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 417.c. See NOAV doc#403161100 dated 09/09/2022. CA date of 10/09/2022 not completed.</div>						Date:		10/09/2022

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403868530	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642322
693807510	Inspection photos 7/23/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642317