

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2024

Submitted Date:

08/07/2024

Document Number:

716200338

## FIELD INSPECTION FORM

 Loc ID: 405923  
 Inspector Name: Carlile, Craig  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456895	TANK BATTERY	AC	08/27/2018		-	BC 13-20,4-20,14-20,24-20,23-20 TB	AO

**General Comment:**

In order to assist with the management of ECMC's enforcement backlog only egregious (i.e. Safety, Pending Environmental Harm or Extreme Circumstance) alleged violations should be submitted initially corrective actions through the inspection document. Using your administrative judgement, "minor alleged violations" should be addressed by using the comment field on the inspection document and/or subsequent (phone or in person) communication with the operator's personnel. If the issue fails to be addressed in a timely manner a new inspection document should be submitted addressing the issue using the corrective action procedures.

This is a routine audit of:

?Wellhead(s)

?Battery

?Drilling

?Fracking

Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	#			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		40.205920,-104.806870
Comment:					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	150 Bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shared with condensate tank.				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 456895 Type: TANK API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>In order to assist with the management of ECMC's enforcement backlog only egregious (i.e. Safety, Pending Environmental Harm or Extreme Circumstance) alleged violations should be submitted initially corrective actions through the inspection document. Using your administrative judgement, "minor alleged violations" should be addressed by using the comment field on the inspection document and/or subsequent (phone or in person) communication with the operator's personnel. If the issue fails to be addressed in a timely manner a new inspection document should be submitted addressing the issue using the corrective action procedures.</p> <p>This is a routine audit of:                      ?Wellhead(s)                      ?Battery                      ?Drilling                      ?Fracking                      Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</p>	carlilec	08/07/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716200339	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6655743">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6655743</a>