

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403879746

Date Received:

08/07/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Lacey Granillo

5057870118

lgranillo@logosresourcesllc.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000993

Inspection Date: 07/24/2024

FIR Submit Date: 07/26/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

### LOCATION - Location ID: 325127

Location Name: MCCARVILLE-N33N9W Number: 23SWNW County: \_\_\_\_\_

Qtrqtr: SWN Sec: 23 Twp: 33N Range: 9W Meridian: N  
W

Latitude: 37.092700 Longitude: -107.801320

### FACILITY - API Number: 05-067- -00 Facility ID: 325127

Facility Name: MCCARVILLE-N33N9W Number: 23SWNW

Qtrqtr: SWN Sec: 23 Twp: 33N Range: 9W Meridian: N  
W

Latitude: 37.092700 Longitude: -107.801320

### CORRECTIVE ACTIONS:

1 ☒ CA# 196984

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 08/08/2024

Response: CA COMPLETED

Date of Completion: 08/06/2024

Operator Comment: Guy line wires properly marked.

ECMC Decision: Approved via an AMI

ECMC Representative:	1. Per photo included in attachment provided by operator the guy line anchors have been marked.		
2	✔	CA# 196985	
Corrective Action:	Comply with rule 1002 Install or repair required BMPs.		Date: 08/01/2024
Response:	CA COMPLETED		Date of Completion: 08/06/2024
Operator Comment:	Repaired BMPs and location.		
ECMC Decision:	Approved pending re-inspection		
ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.		

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	All guy line wires marked. Repaired BMPs and location.
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: Lacey Granillo <span style="float: right;">Signed: _____</span></p> <p>Title: Regulatory Specialist <span style="float: right;">Date: 8/7/2024 9:01:25 AM</span></p>	

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403879746	FIR RESOLUTION SUBMITTED
403879763	Mccarville 1-714000993
403879764	Mccarville 1-714000993
403879765	Mccarville 1-714000993
403879767	Mccarville 1-714000993
403879768	Mccarville 1-714000993

Total Attach: 6 Files