

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403884290

Date Received:
08/09/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
 3 of 3 CAs from the FIR responded to on this Form
 3 CA Completed
 0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: <u>10071</u>	Contact Name and Telephone:
Name of Operator: <u>HIGHPOINT OPERATING CORPORATION</u>	Name: _____
Address: <u>555 17TH ST STE 3700</u>	Phone: () _____ Fax: () _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 682404594
 Inspection Date: 02/28/2019 FIR Submit Date: 03/06/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
 Address: 1099 18TH ST STE 2300
 City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 444078

Location Name: Randall Creek Number: 29 County: _____
 Qtrqtr: SESE Sec: 29 Twp: 12N Range: 62W Meridian: 6
 Latitude: 40.974064 Longitude: -104.337883

FACILITY - API Number: 05-123-00 Facility ID: 444078

Facility Name: Randall Creek Number: 29
 Qtrqtr: SESE Sec: 29 Twp: 12N Range: 62W Meridian: 6
 Latitude: 40.974064 Longitude: -104.337883

CORRECTIVE ACTIONS:

1	CA# <u>122981</u>	
Corrective Action:	<u>Comply with Rule 1002.c. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.</u>	Date: <u>02/28/2019</u>
Response:	<u>CA COMPLETED</u>	Date of Completion: <u>07/22/2024</u>
Operator Comment:	<u>Operator has completed actions pertaining to weed management and maintenance of location to comply with the 1000 series.</u>	
ECMC Decision:	_____	

ECMC
Representative:

2 CA# 122982

Corrective Action: Operator shall immediately stabilize the well pad area to abide by Rule 1002 e.(1), as the location should be in compliance at all times. Long-term well pad stabilization shall be implemented.

Date: 02/28/2019

Operator shall take measures to comply with Rule 1004 and control wind erosion throughout the impacted deposition areas off Location.

Response: CA COMPLETED

Date of Completion: 07/22/2024

Operator Comment: Operator has completed actions pertaining to weed management, erosion and overall maintenance of the location to comply with the 1000 series.

ECMC Decision:

ECMC
Representative:

3 CA# 122983

Corrective Action: Comply with Rule 1003.b. Corrective action date is being back dated to when Interim Reclamation activities should have been completed.

Date: 03/31/2018

Response: CA COMPLETED

Date of Completion: 07/22/2024

Operator Comment: Operator has completed actions pertaining to reclamation to comply with the 1000 series.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 8/9/2024 12:24:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403884311	Inspection Report Resolution
-----------	------------------------------

Total Attach: 1 Files