

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2024

Submitted Date:

08/08/2024

Document Number:

699506139**FIELD INSPECTION FORM**Loc ID 318799 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242183	WELL	SI	11/01/2023	GW	123-09974	J.E. KIRKMEYER 1	SI

General Comment:[There have been no changes to equipment on location since previous inspection.](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:		Date: _____		
Good Housekeeping:				
Type	WEEDS			
Comment:		weeds unmanaged		
Corrective Action:		Comply with rule 606		Date: 09/08/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:		Date:		
Flaring:				
Type				
Comment:				
Corrective Action:		Date:		

Inspected Facilities

Facility ID: 242183

Type: WELL

API Number: 123-09974

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/05/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>ECMC Inspection Report Summary</div> <div>On 8/8/24 I, Inspector Justin Medina conducted an on-site inspection at:</div> <div>Well Name- J.E. Kirkmeyer 1</div> <div>Company Name- KPK</div> <div>API- 05-123-09974</div> <div>In Weld County Colorado.</div> <div>While there, I observed Well Type</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>Weeds. Comply with rule 606. 9/8/24</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</div> <div>This is a summary of inspection report.</div>	medinaj	08/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403888824	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6664765
699506140	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6664749