

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2024

Submitted Date:

08/21/2024

Document Number:

713601337**FIELD INSPECTION FORM**Loc ID 321659 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments5 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Enforcement		dnr_ecmcenforcement@state.co.us	
GROWNS LARRY		lgrowns@willifordenergy.com	
Storts, Doug		pds@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207701	WELL	PR	11/11/2008	OW	017-06636	RHOADES UNIT 4-5	RI
321659	LOCATION	AC			-	RHOADES 44-31-613S48W 31SESE	RI

General Comment:

This is a follow up of the previous inspections; #713600865, #713601097.
The corrective actions of the previous inspections have not been completed.
Non-compliance with the Rules will be referred to enforcement.

Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Lease Road:			
Type	Access		
comment:	There are areas where vehicles are driving outside of the access road boundary causing unnecessary disturbance that will need to be reclaimed. Repeated or flagrant instance(s) of failure to restrict lease access to lease roads which result in unreasonable land damage or crop losses shall be subject to a penalty under Rule 523. Vehicle tracks were observed outside of the access road boundary. Previous corrective action was not completed.		
Corrective Action	Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.	Date:	

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	There are oily rags and gloves next to the pumpjack that must be properly disposed.		
Corrective Action:	Comply with Rule 606	Date:	
Type	OTHER		
Comment:	The electric utility is not maintained in a safe manner. The electric wire is laying on the ground and not connected to the breaker box.		
Corrective Action:	Comply with 608.e. to maintain in good mechanical condition.	Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil	Pump Jack			
Comment:	The previous inspection observed oil leaking out of the pumpjack engine. It appears this leak has been ongoing for a duration of time and there is oil saturated soils. The pumpjack engine has since been removed. There are still oil stained soils that have not been cleaned up and properly disposed.			
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906.			Date:

In Containment: No

Comment:

☒ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
			Fail	Material Handling And Spill Prevention	Fail	

Comment: There are areas of access road which are not stabilized or maintained. There are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base and culverts. The roads needs to be built up to allow stormwater drainage. Previous corrective action was not completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601338	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673051