

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2024

Submitted Date:

08/21/2024

Document Number:

713601341

FIELD INSPECTION FORM

Loc ID 321605 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96730
 Name of Operator: WILLIFORD ENERGY COMPANY
 Address: 6060 AMERICAN PLAZA SUITE 760
 City: TULSA State: OK Zip: 74135

Findings:

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Storts, Doug		pds@willifordenergy.com	
GROWNS LARRY		lgrowsn@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207475	WELL	IJ	12/30/2011	ERIW	017-06410	RHOADES UNIT TRACT 3 1	RI

General Comment:

[This is a location and stormwater management inspection of the RHOADES Unit Tract 3 #1 wellsite. See attached photos and additional details within this report](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	The well sign is faded and not legible		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/21/2024

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	There is oil stained soil at the wellhead that must be cleaned up.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	08/30/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	The fence at the solar panel needs maintenance.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	08/30/2024

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
			Fail	Material Handling And Spill Prevention	Fail	

Comment: There are areas of access road which are not stabilized or maintained. There are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base and culverts. There is a chemical barrel with no secondary containment.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 08/30/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601342	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673245