

WELL NAME: BREWER FEDERAL 2-17, API #: 033-06108, INSP. # 695110172



PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID. UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.



WGS84
±16ft

37.64385, -108.96125

ft
±10ft

6667

°M
±14

SW202

Colorado Oil & Gas Conservation commission
© 25-Aug-24 13:37:03

PHOTO 2: LOCATION/



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources




PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 3: TANK BATTERY





PHOTO 5: VEHICLE TRACKING AND STORM WATER HAVE ERODED ROW AND IS CAUSING VEHICLE TO SIDETRACK AND MAKE ROAD WIDER. REPAIR ROW AND INSTALL BMP'S TO PREVENT VEHICLE TRACKING AND STORMWATER EROSION PER RULE 1002.