

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2024

Submitted Date:

08/21/2024

Document Number:

693807665

**FIELD INSPECTION FORM**

Loc ID 324056 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 51130  
Name of Operator: LOCIN OIL CORPORATION  
Address: 600 TRAVIS STREET SUITE 5050  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Gross, Jason		jgross@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211597	WELL	SI	06/01/2020	GW	045-07358	FEDERAL 27-12	SI

**General Comment:**

ECMC staff performed a routine field inspection on 8/15/2024.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL		Date:	
Type	Main		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Previous inspections observed that signage/labels at the 300 bbl condensate tank does not comport with Rule 605.h; Operator information incorrect. This corrective action has not been addressed and remains applicable.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	12/15/2022
Type	TANK LABELS/PLACARDS		
Comment:	Previous inspections observed that signage/labels at the open-top produced water tank does not comport with Rule 605.h; Operator information incorrect. This corrective action has not been addressed and remains applicable.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	12/15/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-858-7546 CA from previous inspection completed		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Empty metal barrels stored around wellhead. Stored equipment for reclamation project on 05-045-06107 pad.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Livestock fence around blowdown tank		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment: <span style="color:blue;">Pipe fence</span>			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.422104,-108.978964
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 211597 Type: WELL API Number: 045-07358 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well shut in 6/1/2020  
Alternative MIT form 4 Doc#403054060 submitted 5/23/2022. Approved 9/12/2022.  
Inactive well notice doc#403291660 submitted 01/16/2023.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/03/2024 Annual Brhd Completed? Yes  
Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403896658	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673550">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673550</a>
693807666	Inspection photos 8/15/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673540">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673540</a>