

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2024

Submitted Date:

08/29/2024

Document Number:

713601399

FIELD INSPECTION FORM

Loc ID 480451 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
 Name of Operator: CITATION OIL & GAS CORP
 Address: 14077 CUTTEN RD
 City: HOUSTON State: TX Zip: 77069

Findings:

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Steffy Goncalves		SGoncalves@cogc.com	
CITATION		ENV-CODNR@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480416	TANK BATTERY	AC	08/16/2021		-	Arapahoe Unit Tank Battery	RI

General Comment:

This is a reclamation inspection at the Arapahoe Unit Tank Battery.
 See attached photos and additional details within this report

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	The tank labels are faded and/or missing.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/30/2024

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment stored on location that must be removed.		
Corrective Action:	Comply with Rule 606.	Date:	09/20/2024
Type	OTHER		
Comment:	There are chemical containment with oily sludge and no wildlife protections.		
Corrective Action:	Clean up leaked fluid and install wildlife protection/netting per Rule 902.b.	Date:	09/20/2024

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	There was an oil leak that occurred at the back side of the tank battery that was contained inside the secondary containment. There is also oil stains around the other tanks and at the pipe outlet.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact EPS staff per Rule 912.b. 24 hours to remove free fluids. 24 hours for notification and 72 hours for Initial Form 19 Report.		Date: 09/03/2024

In Containment: Yes _____

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601400	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6687104