

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403849341

Date Received:

07/16/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Tyler Faldyn	832-748-1090	tfaldyn@americanhelium.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 699700370
Inspection Date: 05/06/2024 FIR Submit Date: 05/16/2024 FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 323896

Location Name: FEDERAL-68S104W Number: 10NWNW County: _____
Qtrqtr: NWN Sec: 10 Twp: 8S Range: 104W Meridian: 6
W
Latitude: 39.388355 Longitude: -108.982622

FACILITY - API Number: 05-045- -00 Facility ID: 323896

Facility Name: FEDERAL-68S104W Number: 10NWNW
Qtrqtr: NWN Sec: 10 Twp: 8S Range: 104W Meridian: 6
W
Latitude: 39.388355 Longitude: -108.982622

CORRECTIVE ACTIONS:

1 CA# 195215

Corrective Action: Comply with Rule 1002.f.(2)- Install or repair required stormwater and erosion control BMPs to properly divert stormwater runoff, and well as to stabilize the working pad surface, and to minimize tracking and off-site sediment transport. Ensure BMPs are installed in accordance with good engineering practices and maintained in a proper functioning condition; ongoing stormwater management required until Location receives a passing final reclamation inspection.

Date: 07/17/2024

Response: CA COMPLETED Date of Completion: 07/16/2024

Locin hired Energy Field Services as a contractor to complete the stormwater repair. Please see attached photos.

Comment:	Location is in Garfield county.
----------	---------------------------------

Print Name: Niah Wilson Signed: _____
Title: Regulatory Specialist Date: 7/16/2024 2:20:03 PM

<u>Document Number</u>	<u>Description</u>
403849341	FIR RESOLUTION SUBMITTED
403856470	Images of stormwater repair

Page 2 of 2