

Inspection Photos

Operator: Simcoe LLC

Location Name: Buford Wayt A 2 API: 067-09075

Location Name: Buford Wayt A 4 API: 067-09092



Brian Welsh SE Field Inspector COGCC
37.14451, -107.65439, 6543.6ft
08/28/2024 14:14:18

1. Location overview



Brian Welsh SE Field Inspector COGCC
37.14473, -107.65456, 6541.1ft
08/28/2024 14:16:21

2. Pumping units

Inspection Photos

Operator: Simcoe LLC

Location Name: Buford Wayt A 2 API: 067-09075

Location Name: Buford Wayt A 4 API: 067-09092



3. Production equipment



4. Water tank

Inspection Photos

Operator: Simcoe LLC

Location Name: Buford Wayt A 2 API: 067-09075

Location Name: Buford Wayt A 4 API: 067-09092



Brian Welsh SE Field Inspector COGCC
37.1449, -107.65486, 6546.5ft
08/28/2024 14:21:08

5. Erosion on the west side of location needs to be repaired



Brian Welsh SE Field Inspector COGCC
37.14475, -107.6549, 6548.8ft
08/28/2024 14:21:27

6. Erosion on the southwest corner of location needs to be repaired