

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2024

Submitted Date:

09/05/2024

Document Number:

714300116

**FIELD INSPECTION FORM**Loc ID 317973 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21
Anderson, Laurel		laurel.anderson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485680	SPILL OR RELEASE	AC	12/20/2023		-	Production Tank	EI

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 485680. Inspection submitted to document site conditions at the time of inspection.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds present throughout location		
Corrective Action:	Comply with Rule 606.	Date:	09/12/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	No fencing is present around open excavation.		
Corrective Action:	Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B. Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.	Date:	09/12/2024

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	485680	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Shallow open excavation remains present on location. Per last report soil impacts greater than Table 915-1 have been remain in situ and have not been delineated. Form 27 Doc No 403772874 (submitted 8/14/2024) In Process for this location.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type \_\_\_\_\_ Management \_\_\_\_\_ Condition \_\_\_\_\_ GPS (Lat) (Long) \_\_\_\_\_

Comment	<span style="color: blue;">No E&amp;P waste stockpiled on location.</span>
Corrective Action	
	Date: _____

**Spill/Remediation:**Comment: Spill ID 485680 remains open.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19± Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director

Date: 01/04/2024

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300117	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695209">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695209</a>