

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403913679

Date Received:

09/09/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 717700360

Inspection Date: 09/03/2024

FIR Submit Date: 09/03/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 437854

Location Name: Anschutz Equus Farms

Number: 4-62-33
NWNW

County: _____

Qtrqr: NWN Sec: 33 Twp: 4N Range: 62W Meridian: 6
W

Latitude: 40.273303 Longitude: -104.337575

FACILITY - API Number: 05-123- -00

Facility ID: 437854

Facility Name: Anschutz Equus Farms

Number: 4-62-33
NWNW

Qtrqr: NWN Sec: 33 Twp: 4N Range: 62W Meridian: 6
W

Latitude: 40.273303 Longitude: -104.337575

CORRECTIVE ACTIONS:

1 CA# 198282

Corrective Action: Comply with the 1100 rules

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 09/06/2024

Operator Comment: Operator has addressed the issue and future use tags have been installed on all unused risers in order to comply with the 1100 series.

ECMC Decision: _____

ECMC
Representative:

2 CA# 198283

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 09/06/2024

Operator
Comment:

Operator has addressed the issue and the soil next to the compressor has been cleaned up in order to comply with Rule 905.e.

ECMC Decision: _____

ECMC
Representative:

3 CA# 198284

Corrective Action: Install sign to comply with Rule 605.h.

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 09/06/2024

Operator
Comment:

Operator has addressed the issue and capacity labels on all pits have been replaced in order to comply with Rule 605.h.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 9/9/2024 12:05:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403913683	Inspection Report Resolution
-----------	------------------------------

Total Attach: 1 Files