

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2024

Submitted Date:

09/06/2024

Document Number:

710500334

FIELD INSPECTION FORM

Loc ID 334200 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num:

Operator Information:

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258523	WELL	PR	12/08/2001	CBM	071-07098	SILVERLAND 31-22	EI
288806	WELL	PR	04/03/2007	CBM	071-09156	SILVERLAND 31-22 TR	EI
301239	PIT	AC			-	SILVERLAND 31-22 TR	EI

General Comment:

This is a follow up Environmental Inspection for the Silverland 31-22 and Silverland 31-22 TR, well location Located in Las Animas County CO.

Environmental				
Waste Management:				
Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Other			
Comment	Per COA outlined in inspection Document # 710500319; There is a pile of grey material located on the southwest corner of the well pad. The material appears to be E&P Waste excavated from the pit. In addition, the same material is located on the working surface of the well pad. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.Contact ECMC EPS staff.			
Corrective Action	Operator has not supplied analytical data in a FIRR as discussed with area EPS. Operator shall supply analytical data in a Form 27 Supplemental Filing under remediation project # 33165.			Date: 09/11/2024
Spill/Remediation:				
Comment:				
Corrective Action:				Date: _____
Emission Control Burner (ECB): _____				
Comment:				
Pilot: _____	Wildlife Protection Devices (fired vessels): _____			

Comment	User	Date
The Fencing for Pit Facility ID 261321 has been removed. Corrective action is completed.	sanchezcc	09/06/2024

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403912628	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6696217
710500335	Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6696201