

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403868085

Date Received:

07/30/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

6 of 7 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 55030

Name of Operator: MCCARTNEY ENGINEERING LLC

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

McCartney, Ron

303-830-7208

ron@mccartneyengineering.com

McCartney, Jack

303-830-7208

jack@mccartneyengineering.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 709100333

Inspection Date: 06/26/2024

FIR Submit Date: 07/09/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: MCCARTNEY ENGINEERING LLC

Company Number: 55030

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

#### LOCATION - Location ID: 317041

Location Name: WARREN\*S J-62N49W Number: 11NWSW County: \_\_\_\_\_

Qtrqtr: NWS Sec: 11 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.154066 Longitude: -102.830999

#### FACILITY - API Number: 05-121-00 Facility ID: 317041

Facility Name: WARREN\*S J-62N49W Number: 11NWSW

Qtrqtr: NWS Sec: 11 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.154066 Longitude: -102.830999

### CORRECTIVE ACTIONS:

1 CA# 196616

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/18/2024

Operator Comment: Rodent burrows in berm closed, berm repaired.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 196617

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/18/2024

Operator  
Comment: Soiled dirt removed, no visible leaks.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 196618

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/18/2024

Operator  
Comment: Soiled dirt removed, no visible leaks.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 196620

Corrective Action: Comply with Rule 606.

Date: 07/16/2024

Response: CA COMPLETED

Date of Completion: 07/18/2024

Operator  
Comment: Plastic pit liner pushed into berm by COGCC when cleaning up oil contaminated soil several years ago. Pit liner material removed and berm reshaped. Gallon container removed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**6** CA# 196621

Corrective Action: Comply with Rule 606

Date: 07/11/2024

Response: CA COMPLETED

Date of Completion: 07/18/2024

Operator  
Comment: 2" pipe removed from location.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**7** CA# 196622

Corrective Action: Install wildlife screen and prevent entry by wildlife, per Rule 608.b.(7).

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/18/2024

Operator Comment: Tin that blew off treater shed replaced prior to receiving this inspection notice. Pigeons removed from their roost and pigeon poop cleaned up.

ECMC Decision:

ECMC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Field Inspection Form was received via email to our office on 7/16/2024, an extension of time to complete certain items was given and all items were corrected on time. Factual review was requested on 7/29/24 via email on the remaining item.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jack McCartney

Signed:

Title: Manager

Date: 7/30/2024 2:52:11 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403868085	FIR RESOLUTION SUBMITTED
403871109	Pictures

Total Attach: 2 Files