

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403920674

Date Received:

09/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10671

Name of Operator: EDGE ENERGY II LLC

Address: 600 12TH STREET SUITE 115

City: GOLDEN State: CO Zip: 80401

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Turner, Ben

bturner@edgeenergy1.com

Kelsi Welch

Kelsi.welch@iptwell.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 679603454

Inspection Date: 11/09/2020

FIR Submit Date: 11/09/2020

FIR Status: _____

Inspected Operator Information:

Company Name: EDGE ENERGY II LLC

Company Number: 10671

Address: 1301 WASHINGTON AVE SUITE 300

City: GOLDEN State: CO Zip: 80401-6138

LOCATION - Location ID: 457767

Location Name: Simpson Number: 26 Pad County: _____

Qtrqtr: NESE Sec: 26 Twp: 8N Range: 66W Meridian: 6

Latitude: 40.632960 Longitude: -104.735970

FACILITY - API Number: 05-123-00 Facility ID: 457767

Facility Name: Simpson Number: 26 Pad

Qtrqtr: NESE Sec: 26 Twp: 8N Range: 66W Meridian: 6

Latitude: 40.632960 Longitude: -104.735970

CORRECTIVE ACTIONS:

1 CA# 144626

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 02/09/2021

Response: CA COMPLETED

Date of Completion: 02/09/2021

Operator
Comment:

CA was completed. Please reference follow up inspection doc #679603768 for confirmation of completed CA.

ECMC Decision: _____

ECMC
Representative:

2 CA# 144627

Corrective Action: Install sign to comply with Rule 210.d.

Date: 12/09/2020

Response: CA COMPLETED

Date of Completion: 12/09/2020

Operator
Comment:

CA was completed. Please reference follow up inspection doc #679603768 for confirmation of completed CA.

ECMC Decision: _____

ECMC
Representative:

3 CA# 144628

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 02/09/2021

Response: CA COMPLETED

Date of Completion: 02/09/2021

Operator
Comment:

CA was completed. Please reference follow up inspection doc #679603768 for confirmation of completed CA.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This is a retroactive submission to formally resolve the subject inspection and for compliance with Rule 210.b.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch

Signed: _____

Title: Permitting & Compliance

Date: 9/13/2024 1:50:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files