

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403873543

Date Received:  
08/01/2024

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 693700441  
Inspection Date: 04/28/2020 FIR Submit Date: 04/30/2020 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

**LOCATION** - Location ID: 415772

Location Name: Garden Creek Number: 06-11H County: \_\_\_\_\_  
Qtrqtr: SESE Sec: 11 Twp: 11N Range: 62W Meridian: 6  
Latitude: 40.931011 Longitude: -104.279628

**FACILITY** - API Number: 05-123-00 Facility ID: 415772

Facility Name: Garden Creek Number: 06-11H  
Qtrqtr: SESE Sec: 11 Twp: 11N Range: 62W Meridian: 6  
Latitude: 40.931011 Longitude: -104.279628

**CORRECTIVE ACTIONS:**

**1** CA# 138560

Corrective Action: Cleanup spill and identify cause of release ECD and repair Date: 05/28/2020

Response: CA COMPLETED Date of Completion: 07/26/2024

Operator Comment: Operator has provided follow-up to show that noted spill has been appropriately addressed to comply with the 900 series.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 138561

Corrective Action: Submit confirmation soil samples with analysis for TPH (C6-36) and BTEX from spill area on a Form 19 Supplemental Report along with root cause of separator overpressure.

Date: 05/15/2020

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided follow-up to show that noted spill was appropriately addressed and Form 19 Doc #: 402275143 was submitted.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 8/1/2024 9:52:02 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403873543	FIR RESOLUTION SUBMITTED
403873560	Inspection Report Resolution

Total Attach: 2 Files