

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403873612

Date Received:  
08/01/2024

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 684901452  
Inspection Date: 06/08/2016 FIR Submit Date: 06/08/2016 FIR Status: ACTION REQUIRED

**Inspected Operator Information:**

Company Name: EOG RESOURCES INC Company Number: 27742  
Address: 600 17TH ST STE 1100N  
City: DENVER State: CO Zip: 80202

**LOCATION** - Location ID: 415939

Location Name: Randall Creek Number: 04-32H County: \_\_\_\_\_  
Qtrqr: NENE Sec: 32 Twp: 12N Range: 62W Meridian: 6  
Latitude: 40.972000 Longitude: -104.339189

**FACILITY** - API Number: 05- - -00 Facility ID: 418732

Facility Name: \_\_\_\_\_ Number: \_\_\_\_\_  
Qtrqr: NENE Sec: 32 Twp: 12N Range: 62W Meridian: 6  
Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

**CORRECTIVE ACTIONS:**

**1** CA# 50396

Corrective Action: Install sign to comply with rule 210. Date: 08/08/2016

Response: CA COMPLETED Date of Completion: 07/26/2024

Operator Comment: Operator has installed appropriate signage on production tank to comply w/ ECMC Rule 605.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 50397

Corrective Action: mark deadmen or remove

Date: 06/23/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has appropriately installed a marker for the identified deadman.

ECMC Decision:

ECMC  
Representative:

**3** CA# 50398

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 07/08/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided follow-up to show that location complies with Rule 1002.f.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 8/1/2024 10:21:39 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403873612	FIR RESOLUTION SUBMITTED
403873696	Inspection Report Resolution

Total Attach: 2 Files