

**State of Colorado**  
**Energy & Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403925065

Date Received:

09/17/2024

**FIR RESOLUTION FORM**

**Overall Status:**

**CA Summary:**

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 55030

Name of Operator: MCCARTNEY ENGINEERING LLC

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

Amber Barnett

abarnett@ardorenvironmental.com

Krystal Heibel

krystal.heibel@state.co.us

Lisa McCartney

lisa@mccartneyengineering.com

Jack McCartney

jack@mccartneyengineering.com

Kyle Waggoner

kyle.waggoner@state.co.us

Ron McCartney

ron@mccartneyengineering.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 709100390

Inspection Date: 09/10/2024

FIR Submit Date: 09/17/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: MCCARTNEY ENGINEERING LLC

Company Number: 55030

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

**LOCATION - Location ID: 302966**

Location Name: SEEDORF-62N48W Number: 21NWNE County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 21 Twp: 2N Range: 48W Meridian: 6

Latitude: 40.130957 Longitude: -102.744856

**FACILITY - API Number: 05-125- -00 Facility ID: 302966**

Facility Name: SEEDORF-62N48W Number: 21NWNE

Qtrqtr: NWNE Sec: 21 Twp: 2N Range: 48W Meridian: 6

Latitude: 40.130957 Longitude: -102.744856

**CORRECTIVE ACTIONS:**

1 CA# 198823

Corrective Action: Outside of crop season, maintain lease road to comply with rule 204.

Date: 12/16/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator Comment: The Seedorf #1 was P&A'd 10/19/2023. Shortly thereafter, the casing was cut off and capped, all lines and surface equipment removed. The flowline ROW and lease road were leveled and disked to accommodate ongoing farming operations. At the time of inspection, the field was plowed with organic fertilizer applied in preparation of wheat planting.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

2 CA# 198824

Corrective Action: In accordance with Rule 913.e.(3), Operator shall submit a Form 27 Supplemental quarterly (every 90 days) to remediate any spill/release and/or to close the remediation project.

Date: 10/16/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator Comment: Form 27 Supplemental was submitted on 7/31/2024 detailing numerous soil samples analyzed to assist in determining the lateral and vertical extent of a saltwater spill. Additional soil samples have been taken for analysis to further define the extent of the spill. Results of continued remediation work will be timely reported on another Form 27.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: There is a small area of saltwater contamination with additional soil samples being analyzed to determine the lateral and vertical extent of contamination. The area was treated with organic material in conjunction with consultation with the landowner to augment fall wheat growth. Remediation plan will be timely submitted once the spill area is defined.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jack McCartney

Signed: \_\_\_\_\_

Title: Manager

Date: 9/17/2024 4:19:35 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files