

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2024

Submitted Date:

09/29/2024

Document Number:

708904697**FIELD INSPECTION FORM**Loc ID 335488 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	PR

General Comment:**CECMC Inspection Report Summary**

On 09/25/2024 at approximately 13:00 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RWF 43-26 Pad.
Location # 335488 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed workover rig tripping in to set plug & do casing repair on th SAVAGE RWF 43-26 well API # 05-045-17054

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Rig sign at intersection of public road & start of lease road Additional rig signs at each intersection thereafter		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Other	# 1			
Comment:	Workover rig			
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Accumulator			
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Rig pump			
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Rig tank			
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	500 bbl frac tank			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	298070	Type:	WELL	API Number:	045-17054	Status:	PR	Insp. Status:	PR

Workover

Comment:

Observed workover rig tripping in to set plug & do casing repair.

Please refer to FORM 42 document # 403922641 submitted on 09/16/2024 - NOTICE OF MOVE-IN, RIG-UP submitted by operator had a start date of 09/18/2024 but rig arrived on location approximately 6-7 days later & a revised FORM 42 was never submitted by the operator to reflect the new start date as required. However I was contacted by TEP workover consultant & informed the rig blew a hydraulic pump & needed repairs before the rig would be on location. The consultant stayed in contact with me & gave me updates on the rig & possible ETA.

Failure to update forms as required may result in corrective actions in future inspections.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <div>Limited inspection due to ongoing workover operations on location</div>						Date: _____
Corrective Action: <div></div>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
Please refer to Inspected Facilities for comments.	smelserw	09/29/2024
Limited inspection due to ongoing workover operations on location		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904698	Inspection 708904697 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6726430