

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403922644

Date Received:

09/16/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BACA, DAVE

719-859-4066

dbaca@ogrisop.com

ZECHES, GIENA

719-220-4041

GZECHES@OGRISOP.COM

ECMC INSPECTION SUMMARY:

FIR Document Number: 695109498

Inspection Date: 04/22/2024

FIR Submit Date: 04/22/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 307949

Location Name: HILL RANCH-635S67W Number: 10SESW County: LAS ANIMAS

Qtrqtr: SESW Sec: 10 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.006340 Longitude: -104.877990

FACILITY - API Number: 05-071- -00 Facility ID: 259818

Facility Name: HILL RANCH Number: 10-14V

Qtrqtr: SESW Sec: 10 Twp: 35S Range: 67W Meridian: 6

Latitude: 37.006340 Longitude: -104.877990

CORRECTIVE ACTIONS:

1 CA# 194489

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D.

Date: 05/22/2024

Response: CA COMPLETED

Date of Completion: 05/21/2024

Operator Comment: MAINTENANCE HAS BEEN PERFORMED ON ALL EQUIPMENT, THE IMPACTED SOIL HAS BEEN REMOVED AND THE CONCRETE RISER PAINTED.

ECMC Decision: _____

ECMC
Representative: _____

2 CA# 194490

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 05/22/2024

Response: CA COMPLETED

Date of Completion: 05/21/2024

Operator Comment: MECHANICAL MAINTENANCE HAS BEEN PERFORMED ON THE LEAKING GEARBOX AT THE PUMPJACK AND THE SKID HAS BEEN CLEANED OF ANY OIL.

ECMC Decision: _____

ECMC
Representative: _____

3 CA# 194491

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 04/23/2024

Response: CA COMPLETED

Date of Completion: 05/21/2024

Operator Comment: MECHANICAL MAINTENANCE HAS BEEN PERFORMED ON THE LEAKING GEARBOX AT THE PUMPJACK AND THE SKID HAS BEEN CLEANED OF ANY OIL.

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 9/16/2024 2:23:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403922644	FIR RESOLUTION SUBMITTED
403922651	PHOTO LOG

Total Attach: 2 Files