

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2024

Submitted Date:

10/11/2024

Document Number:

712300088

FIELD INSPECTION FORMLoc ID 324766 Inspector Name: Maxwell, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10761

Name of Operator: WOODBURY RESOURCES LLC

Address: 190 ORANGE STREET

City: AUBURN State: CA Zip: 95603

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jack@woodburyresources.co	
		kris.neidel@state.co.us	
		chris.binschus@state.co.us	
		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324766	LOCATION	AC			-	Fuqua 18-15 Pad	RI

General Comment:

On 9/10//2024, Eastern Reclamation Work Lead Binschus and Reclamation Specialist Maxwell conducted an Interim Reclamation and Stormwater inspection at Woodbury Resource's Fuqua 18-15 Pad Oil and Gas Location in Jackson County, Colorado. This inspection is a follow-up to #697505273 dated 4/15/2024, to document compliance with the following corrective actions:

- Interim Reclamation
- Stormwater Management
- Wildlife
- Signage

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Any corrective actions from previous inspections that have not been addressed remain applicable. Any new corrective actions without corrective action dates, requires that the Operator comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	<p>Pursuant to Rule 605.a, from the time of construction until Reclamation is complete, the Operator will post a sign at the entrance to an Oil and Gas Location.</p> <p>At the time of this inspection, it was observed the sign at the Location entrance needs to be corrected due to an inaccurate Well API #.</p>		
Corrective Action:	Comply with Rule 605.a.	Date:	
Type	WELLHEAD		
Comment:	<p>Pursuant to Rule 605.d, from the time of construction until Reclamation is complete, the Operator will post a sign at the wellhead of an Oil and Gas Location.</p> <p>At the time of this inspection, it was observed the sign at the wellhead needs to be corrected due to an inaccurate Well API #.</p>		
Corrective Action:	Comply with Rule 605.d.	Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Unmanaged weeds (e.g., Russian thistle and Canada thistle) were observed along the perimeter of location and concentrated along the southern area. Refer to the attached inspection photos.</p>		
Corrective Action:	Comply with Rule 606.c. and Rule 1003.f.	Date:	05/27/2024
	Operator should conduct weed management in coordination with additional interim reclamation activities that are required.		

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	<p>At the time of this inspection, it was observed that the barbed wire fencing was inadequate/broken around the perimeter of the Location.</p>		
Corrective Action:	Comply with Rule 603.h.	Date:	

Equipment:			corrective date
Type: Bird Protectors	#		
Comment:	<p>It was observed in this inspection, that caps/covers were missing on the equipment at the tank battery.</p>		
Corrective Action:	Comply with Rule 902.b.	Date:	10/18/2024

Venting:

Yes/No			
--------	--	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 324766 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: It was observed in this inspection that there were two constructed nests (what appeared to be owl nests) on the tank battery walkway. The owl(s) did not appear to be present at the time of inspection, however may return in future nesting seasons. Operator shall consult with CPW for raptor nest timing stipulations prior to commencing production operations or any major disturbance activities.

Corrective Action: _____ **Date:** _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Inspected Facilities									
Facility ID:	324766	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTRURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? Fail Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Based on historic aerial imagery and field observations, it does not appear interim reclamation was ever performed. Areas not needed for production operations consist of annual, weedy vegetation with minimal perennial vegetation that is not reflective of reference area conditions.

Due to the location being within Greater Sage Grouse General Habitat Management Area, Operator shall consult with the Colorado Parks and Wildlife on a CPW-recommended seed mixture for reclamation with the Surface Owner's approval.

Corrective Action

Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a CPW-recommended seed mixture with the surface owner's approval. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Provide the CPW consultation regarding a CPW-recommended seed mixture and the surface owner's approval within the Operator's Field Inspection Report Resolution form per Rule 210.b.

Date 06/03/2024Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%

TRANSECT RESULTS OF REFERENCE AREA%

TOTAL % OF DESIRABLE VEGETATION COVER

VEGETATIVE COVER

Comment:

Corrective Action: Date

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

At the time of this inspection, no erosion issues were observed at location or along the access road.

Corrective Action: Date:

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712300095	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743405