

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/08/2024

Submitted Date:

10/12/2024

Document Number:

708904787

FIELD INSPECTION FORM

Loc ID 324035 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211543	WELL	PR	09/13/1998	GW	045-07303	VASSAR/HEATH RMV 227-27	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 10/08/2024 at approximately 12:29 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC VASSAR/HEATH RMV 227-27 pad. Location # 324035 in Garfield County Colorado. Location is within High Priority/Density Habitat areas/Bald Eagle Nest & Roost Sites & in close proximity to NSO Habitat area. While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/split pad - Wellhead only, production equipment for this well is located on the RMV 34-28 pad location # 323913

Location			
Lease Road:			
	Type Access		
	comment:		
	Corrective ActionL		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type BATTERY		
	Comment: No tank battery on location		
	Corrective Action:		Date:
	Type WELLHEAD		
	Comment: Wellhead sign cracking & showing some signs of peeling but still legible at this time		
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment: 911/970-285-9377		
	Corrective Action:		Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type WELLHEAD		
	Comment: Pipe rail fence		
	Corrective Action:		Date:
Equipment:			
			corrective date
Type: Plunger Lift	# 1		
	Comment: Well on plunger lift		
	Corrective Action:		Date:
Type: Bradenhead	# 1		
	Comment: Taylor plug located on bradenhead, bradenhead valve is accessible. Bradenhead line connected to flow line - FORM 4 Sundry document # 402775848		
	Corrective Action:		Date:
Type: Deadman # & Marked	# 4		
	Comment: Marked		
	Corrective Action:		Date:
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211543 Type: WELL API Number: 045-07303 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap				
		Culverts				
		Gravel				Sparse to none in sections
		Sediment Traps				
		Ditches				
Other	Fail					Small soil stockpile with no BMP's
Gravel						Sparse to none
Compaction						Small amount of light compaction
		Compaction				Small amount of light compaction

Comment: [Small soil stockpile with no BMP's/does not comply with CECMC rules](#)
[Unused dirt berm containment on location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Stormwater for comments	smelserw	10/12/2024
Remote location/split pad - Wellhead only, production equipment for this well is located on the RMV 34-28 pad location # 323913		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904788	Inspection 708904787 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743883
708904789	Inspection 708904787 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743884