

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2024

Submitted Date:

10/17/2024

Document Number:

711901313

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 312230 _____ SCHURE, KYM _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 95620
 Name of Operator: WESTERN OPERATING COMPANY
 Address: 1165 DELAWARE STREET #200
 City: DENVER State: CO Zip: 80204

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219740	WELL	SI	12/01/2021	GW	075-06999	ROBERTS 1	SI

General Comment:

WO RIG ON LOCATION - COMMENCING WITH P&A - DAY (1)

Inspected Facilities

Facility ID: 219740 Type: WELL API Number: 075-06999 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: YETTER WELL

Contractor Phone: 970-522-2885

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: DAY (1) PULLING RODS - UNLAND AND PULL TUBING - PREPARING TO SET CIBP

Corrective Action: _____

Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: COMMENCING WITH P&A

Corrective Action: _____

Date: _____

Workover

Comment: RIG ON LOCATION

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
COMMENCING WITH P&A	schureky	10/17/2024