

**State of Colorado**  
**Energy & Carbon Management Commission**



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403966710

Date Received:  
10/22/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name	Phone	Email
<u>Longworth, Mike</u>		<u>michael.longworth@state.co.us</u>
<u>Bechtolt, Phoebe</u>		<u>pbechtolt@maralexinc.com</u>
<u>O'Hare, Mollie</u>		<u>mollieo@maralexinc.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 700300752

Inspection Date: 10/01/2024 FIR Submit Date: 10/03/2024 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: MARALEX RESOURCES INC Company Number: 53255

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**LOCATION - Location ID: 333566**

Location Name: SHELHAMMER-N33N7W Number: 10NWSW County: \_\_\_\_\_

Qtrqtr: NWS Sec: 10 Twp: 33N Range: 7W Meridian: N

Latitude: 37.115320 Longitude: -107.601250

**FACILITY - API Number: 05-067- -00 Facility ID: 333566**

Facility Name: SHELHAMMER-N33N7W Number: 10NWSW

Qtrqtr: NWS Sec: 10 Twp: 33N Range: 7W Meridian: N

Latitude: 37.115320 Longitude: -107.601250

**CORRECTIVE ACTIONS:**

1 CA# 199262

Corrective Action: Comply with Rules 912 and 913.c

Date: 10/04/2024

Response: CA COMPLETED

Date of Completion: 10/22/2024

Date Run: 10/22/2024 Doc [#403966710]

Operator Comment: Due to inclement weather and shortage of staff we are delayed on this project, but we plan to resume work on this location the first week of November and plan to submit an updated FIRR with photos that following week.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

2 CA# 199263

Corrective Action: Comply with all 900, 1000 and 1100 series rules. Immediately remove fluid from buried vessel and fluid filled spill prevention device. Remove all equipment, tanks, junk, trash and debris. Comply with any existing Form 27 COAs, File new and update existing spill reports and remediation plans. Follow up with environmental and integrity staff. Abandon flowlines. Clean up facility to comply with table 915-1 standards. Reclaim production area of PA well and facility 429650 and tank battery 4777716.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Due to inclement weather and shortage of staff we are delayed on this project, but we plan to resume work on this location the first week of November and plan to submit an updated FIRR with photos that following week.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Due to inclement weather and shortage of staff we are delayed on this project, but we plan to resume work on this location the first week of November and plan to submit an updated FIRR with photos that following week.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mollie O'Hare

Signed: \_\_\_\_\_

Title: E.A.

Date: 10/22/2024 7:46:39 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files