

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403967349

Date Received:

10/23/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 7 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Bongers, Brent	361-935-5633	bbongers@impetroresources.com
Kyle Waggoner		kyle.waggoner@state.co.us
Krystal Heibel		krystal.heibel@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100412

Inspection Date: 09/24/2024

FIR Submit Date: 09/26/2024

FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 313910

Location Name: BOSLEY-61N56W Number: 34SEnw County: _____

Qtrqtr: SENW Sec: 34 Twp: 1N Range: 56W Meridian: 6

Latitude: 40.010234 Longitude: -103.636913

FACILITY - API Number: 05-087-00 Facility ID: 313910

Facility Name: BOSLEY-61N56W Number: 34SEnw

Qtrqtr: SENW Sec: 34 Twp: 1N Range: 56W Meridian: 6

Latitude: 40.010234 Longitude: -103.636913

CORRECTIVE ACTIONS:

1 CA# 199062

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 11/04/2024

Response: CA COMPLETED

Date of Completion: 10/21/2024

Operator Comment: Berms have been repaired.

ECMC Decision: _____

ECMC
Representative:

2 CA# 199063

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 10/25/2024

Response: CA COMPLETED

Date of Completion: 10/21/2024

Operator
Comment:

Hydrocarbons along the base of the Vertical Treater have been properly cleaned and disposed of.

ECMC Decision: _____

ECMC
Representative:

3 CA# 199064

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Date: 10/25/2024

Response: CA COMPLETED

Date of Completion: 10/21/2024

Operator
Comment:

There is at least two feet of freeboard within the pit.

ECMC Decision: _____

ECMC
Representative:

4 CA# 199065

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.c.

Date: 10/25/2024

Response: CA COMPLETED

Date of Completion: 10/18/2024

Operator
Comment:

Form 15 (Document # 403962630) was submitted on 10/18/2024.

ECMC Decision: _____

ECMC
Representative:

5 CA# 199066

Corrective Action: Once water production has resumed to the pit, the operator will collect samples for water quality analysis as specified in Rule 909.j. Sample collection will occur within 30 days of recommencement of water production and will be reported within 3 months of collection, as specified in Rule 909.j.(3).

Date: 10/25/2024

Response: CA COMPLETED

Date of Completion: 10/18/2024

Operator
Comment:

A Form 4 (Document #403962608) was submitted as a notification that a Rule 909.j. sample was not collected for the 2024 reporting year because the associated well (Well Facility #227098) was shut in. Once the well is producing again, sampling and reporting will be conducted in compliance with Rule 909.j. As of this time, it is unknown when the well will be returned to service.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 10/23/2024 12:00:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403967349	FIR RESOLUTION SUBMITTED
403967451	Photolog

Total Attach: 2 Files