

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403970221

Date Received:

10/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Javernick, Salene

salenej@gmail.com

Javernick, James

javernick1@gmail.com

COGCC Enforcement

dnr_cogccenforcement@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 690204427

Inspection Date: 07/13/2023

FIR Submit Date: 07/14/2023

FIR Status: _____

Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

LOCATION - Location ID: 322227

Location Name: SLANOVICH-619S69W Number: 32NWSW County: FREMONT

Qtrqtr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.350170 Longitude: -105.140940

FACILITY - API Number: 05-043-00 Facility ID: 210044

Facility Name: SLANOVICH Number: 32-1

Qtrqtr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.350170 Longitude: -105.140940

CORRECTIVE ACTIONS:

1 CA# 175445

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 09/10/2024

Contaminated soils have been removed and properly disposed of. Tank has been removed. See attached photos.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 175446

Corrective Action: Comply with Rule 606.

Date: 06/07/2023

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator
Comment:

Unused equipment has been removed from the location.

ECMC Decision:

ECMC
Representative:

3 CA# 175447

Corrective Action: Previous Corrective Action to Comply with Rule 605.c. was not completed.

Date: 12/08/2022

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator
Comment:

Inspection conducted May 22, 2023 (Document #690203824) observed that drilling operations had ended and the rig was released from location.

ECMC Decision:

ECMC
Representative:

4 CA# 175448

Corrective Action: Comply with Rule 905. Immediately clean up. Implement or modify BMPs for improved material handling and spill prevention.

Date: 01/24/2023

Response: CA COMPLETED

Date of Completion: 09/16/2024

Operator
Comment:

Drill cuttings have been removed location and properly disposed of.

ECMC Decision:

ECMC
Representative:

5 CA# 175449

Corrective Action: Comply with 1003 Rules.

Date: 07/13/2023

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator
Comment:

Undesirable and noxious weeds are been being managed and controlled.

ECMC Decision:

Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)
--------------------	---

Response: CA COMPLETED

Operator Comment:	Interim Reclamation has commenced and berms have been built up around the location.
-------------------	---

ECMC Decision: _____

Comment:	
----------	--

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 10/25/2024 10:32:59 AM

<u>Document Number</u>	<u>Description</u>
403970221	FIR RESOLUTION SUBMITTED
403970507	Location Photos
403970509	Waste Manifests

Date Run: 10/25/2024 Doc [#403970221]