



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/23/2024
Submitted Date:
10/25/2024
Document Number:
713601566

Loc ID
307553

Inspector Name:
COSTA, RYAN

On-Site Inspection ☐
2A Doc Num:

Operator Information:
ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:
☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
Findings:
2 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
307553	LOCATION	AC			-	ABERT SQUIRREL-634S66W 11SENE	RI

General Comment:
This is a location and stormwater inspection of the ABERT SQUIRREL #42-11 location.

Date Run: 10/25/2024 Doc [#713601566]

Page 1 of 3

Location					
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	
Emergency Contact Number:					
Comment:				Date:	
Corrective Action:				Date:	
Good Housekeeping:					
Type					
Comment:					
Corrective Action:				Date:	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the access road northeast of this wellsite that has eroded and exposed a poly line.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/25/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	257680	849653	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601567	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6760753