

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403881031

Date Received:

10/30/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Byers, Jim

jbyers@blm.gov

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708901060

Inspection Date: 07/17/2023

FIR Submit Date: 07/17/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 335369

Location Name: FEDERAL-66S94W Number: 19NENE County: \_\_\_\_\_

Qtrqtr: NENE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.516479 Longitude: -107.924411

### FACILITY - API Number: 05-045- -00 Facility ID: 335369

Facility Name: FEDERAL-66S94W Number: 19NENE

Qtrqtr: NENE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.516479 Longitude: -107.924411

### CORRECTIVE ACTIONS:

1 CA# 175730

Corrective Action: Comply with Rule 605 & fix or replace sign

Date: 08/16/2023

Response: CA COMPLETED

Date of Completion: 08/07/2023

Operator  
Comment:

Wellhead sign has been replaced. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 175731

Corrective Action: The storage of equipment and supplies not necessary for use on location is prohibited.

Date: 08/01/2023

Response: CA COMPLETED

Date of Completion: 07/19/2023

Operator  
Comment:

Hose has been removed from the secondary containment. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

3 CA# 175732

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 07/31/2023

Response: CA COMPLETED

Date of Completion: 07/19/2023

Operator  
Comment:

Deadman anchor has been marked. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

4 CA# 175733

Corrective Action: Comply with Rule 605 & add correct info to tank label

Date: 09/15/2023

Response: CA COMPLETED

Date of Completion: 07/19/2023

Operator  
Comment:

New label has been placed on the tank. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA# 175730: Wellhead sign has been replaced. Corrective Action complete.  
CA# 175731: Hose has been removed from the secondary containment. Corrective Action complete.  
CA# 175732: Deadman anchor has been marked. Corrective Action complete.  
CA# 175733: New label has been placed on the tank. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 10/30/2024 12:14:07 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403881031	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files