

Dyco Petroleum Corporation



November 13, 1972

RECORDED

NOV 14 1972

COLO. OIL & GAS CONS. COMM.

607 PHILTOWER BUILDING  
TULSA, OKLAHOMA 74103  
918/582-8179

Re: #1 Anderson  
Section 17, T. 1 N., R. 93 W.,  
Rio Blanco, Colorado

Oil and Gas Conservation Commission  
State of Colorado  
Room 237, 1845 Sherman Street  
Denver, Colorado 80203

Gentlemen:

We are enclosing for your files the following information covering the above captioned well:

1. Form 5 - Well Completion Report in Quadruplicate
2. 1 Copy - Open Hole Logs
3. 1 Copy - Drilling Summary
4. 1 Copy - Geological Report
5. 1 Copy - Each Drill-Stem Test

We have checked with our consulting engineer and as of this date it is still too wet to clean up the location. Therefore, Form 4 will follow as soon as the location has been cleaned up.

Very truly yours,

DYCO PETROLEUM CORPORATION

Roy H. Reeves

RHR:ch  
Enclosures



00038435