

This well is in a  
very sensitive area,  
same section as the 2  
Nick Kritzas wells,  
very bad water and  
strong hydrostatic head  
& flow from the Weber  
& upper <sup>+ Maroon</sup> formations.

Watch Carefully!  
Called Rycor Pet. Co. on 8/8/12  
Jim



00038426