

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2024

Submitted Date:

11/12/2024

Document Number:

715800256

FIELD INSPECTION FORM

Loc ID 319005 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		conor.pesicka@state.co.us	
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242679	WELL	SI	05/01/2021	GW	123-10470	ARTHUR STROMQUIST 1	SI

General Comment:

[This is a Follow up wellsite audit/inspection to FIR doc # 715800156.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate, fading and will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	adequate, fading and will need to be replaced in the near future		
Corrective Action:		Date:	_____

Good Housekeeping:

Type			
Comment:	Dead vegetation around the wellsite & pump jack need to be addressed.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 2		
Comment:	electric panel, meter box, transformers & telemetry		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 242679 Type: WELL API Number: 123-10470 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, the well is part of a 901 Order.
Most Recent PR records are from 4-2021. Well Mechanical Integrity Test is overdue. MIT requires 10-day notification via Form 42. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shutin status, the well must be able to demonstrate ability to produce without mechanical intervention. CA date 4/13/2024

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/24/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 38 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 11-12-2024 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc# 715800156. Operator: KP Kauffman Location name: Location ID # 319005 Well Name: Arthur Stromquist 1 API # 05-123-10470 County: Weld Weather: Clear. Location: mostly damp & muddy. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues are now delinquent: 417.b MIT SI wells: CA Date 4-13-2024. See attached photos. Due to Non-Compliance with ECMC rules, this audit/inspection will be referred to ECMC Enforcement.</p>	revasr	11/12/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800257	Location pics	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6783766